

## Scania Irizar PB

- **Date Of Registration** 2005
- **Chassis Make** Scania
- **Chassis Model** K114
- **Transmission** ZF Automatic
- **Body Make** Irizar
- **Body Model** PB
- **Seating** 51
- **Mileage** 1,275,000 – 1,400,000 miles

- No. of coaches available 5 to choose from

05D34184

05D34180

05D26960

05D27987

05D34187

- Full maintenance history
- 5 week safety inspection intervals
- 10 week maintenance intervals
- OE or OEM equivalent replacement parts fitted (except some consumables)
- Euro III
- 51 Reclining Seats with Grab Handles, Magazine Pockets & Footrests
- 3 Point Seatbelts
- Air Conditioning
- Tinted Double Glazed Windows
- Rear Continental Emergency Door
- Powered Locker Doors
- CD Radio PA
- Multi-camera CCTV system
- Reversing camera
- Hanover Destination Displays, Front, Side, Rear
- Engine compartment fire suppression system



## VDL Axial 100

- **Date Of Registration** 2008
- **Chassis Make** VDL
- **Chassis Model** SB4000+ EBS
- **Transmission** ZF AS Tronic
- **Body Make** VDL Berkhoff
- **Body Model** Axial 100
- **Seating** 78+1+1
- **Mileage** 545,000-560,000 miles

- No. of coaches available 5 to choose from

08D70525

08D70152

08D58265

08D65806

08D68906

- Full maintenance history
- 5 week safety inspection intervals
- 10 week maintenance intervals
- OE or OEM equivalent replacement parts fitted (except some consumables)
- Euro IV
- 78 Reclining Seats with Grab Handles, Magazine Pockets & Footrests
- 3 Point Seatbelts
- Pulpit main stairwell access to upper saloon with secondary rear stairwell
- Air Conditioning
- Tinted Double Glazed Windows
- Treebars to upper windscreen
- Wheelchair accessible via entrance door ramp, with retention kit and 4 quick release seats
- Powered nearside luggage bay door with separate manual access door
- CD Radio PA
- Multi-camera CCTV system
- Reversing camera
- Hanover Destination Displays, Front, Side, Rear
- Engine compartment fire suppression system

